

RECEIVED


JUN 16 2009

IDAHO STATE POLICE
ALCOHOL BEVERAGE CONTROL

Paul Waters

Muddys Place (8B-78)


475 Northgate mile
Idaho Falls Id
83406



June 16, 2009

[Signature]

- 1644
WATERS
- Occupant load 145
- 2 exits at least $\frac{1}{2}$ diagonal required
- No flush or surface mount bolts prohibited on exits
- Exit doors shall not require a key or special knowledge
(key lock allowed if you can tell by looking its locked and a sign stating it is to be unlocked during business hours is provided)



Exits must have illuminated signs,
Emergency lighting required.